



INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East, Saskatoon, SK, Canada,

Phone: (306) 653-6600 Fax: (306) 242-5599

- Site Service Report -

Date: June 8, 2009

IRD SO.: 10785

From: Darren Thiessen

IRD Contract No.:

To: Bruce Myers, Cindy Mantie

Project Name/Location: Madison County I-40 LTPP (TN)

Service Date(s): December 2, 2008

Job Description: IRD Had reported a problem with the temperature sensor not reporting the temperature accurately. A site visit is needed to assess this problem, and also to perform the fall maintenance.

Work Completed:

- Observed that the system was operating properly (i.e. collecting vehicle records, etc.).
- Moved the temperature sensor from in the conduit near the road surface to against the pull box lid nearest the road.
- Temperature appears to be more accurate with what the road surface temperature is.
- Verified measurements of Loops, Power, etc.
- Site is in excellent shape.
- Site is fully operational.

Work Remaining: None.

Parts Used: None.

Mileage / Travel Time: 11hrs travel / 2 hrs on site.

Notes:

Action Items:

Item	Action Required	Ownership
1.		
2.		
3.		
4.		